



Notice

When generating output, it is no need to isolate the zero-line with the earthing wire, that is to say leave the "14V+" port alone. At that time, make no difference to generating ,while the isolation circuit plays no role on it.