44

AW97CT

NO	. DESCRIPTION	NO.	DESCRIPTION
1	MAIN BADY	24	FIXED NUT
2	BACK COVER	25	NUT
3	TRANSFORMER	26	INNER HEXAGONAL SCREW
4	WELDING HANDLE	27	ROUND CROSS SCREW
5	WELDING PRESS BOARD	28	NUT
6	WELDING POLE	29	SPRING WASHER
7	SPOT WELD ELECTRODE	30	FLAT WASHER
8	SWITCH OF SPOT WELD	31	MAT OF SEPARATE
9	MOVING BODY OF CONNECTION	32	THREAD BAR
10	BLOCK OF UP WELDING POLE	33	BAFFLE
11	PLYWOOD	34	INNER HEXAGONAL SCREW
12	BLOCK OF DOWN WELDING POLE	35	INNER HEXAGONAL SCREW
13	INSULATED BOARD	36	INNER HEXAGONAL SCREW
14	DOWN FIXED PLYWOOD	37	FIXED SCREW
15	PLYWOOD	38	ROUND CROSS SCREW
16	BOLT	39	LINING OF CONNECT SLICE
17	CONNECTING SLICE	40	FIXED RACK OF HANDLE
18	DOWEL	41	BOLT
19	PLUG WITH CABLE	42	HANDLE
20	STRAIN RELIEF	43	MAT OFINSULATED
21	DOWEL	44	COPPER WRING WIRE
22	CLIP SPRING	45	BOLT
23	SCREW	46	ROUND CROSS SCREW

RU7032901

