




# AW97P30

| NO. | DESCRIPTION                      | NO. | DESCRIPTION                    |
|-----|----------------------------------|-----|--------------------------------|
| 1   | HANDLE                           | 28  | BASE SUPPORT                   |
| 2   | ENCLOSURE                        | 29  | BASE PLATE                     |
| 3   | LINKER OF DEPRESSION'S AIR-IN    | 30  | ELECTRIC FAN                   |
| 4   | DECOMPRESSION OF AIR ULTRATE     | 31  | CONNECTION TERMINAL            |
| 5   | CONTROL SILICON SPRING BOARD     | 32  | CAPACITOR                      |
| 6   | CONTROL SILICON                  | 33  | FIXER                          |
| 7   | RADIATOR                         | 34  | CORD                           |
| 8   | CAPACITY                         | 35  | SOLENOID VALVE                 |
| 9   | FIXING BRACKET FOR CAPACITY      | 36  | PNEUMATIC VALVE                |
| 10  | TEMPERATURE CONTROLLER           | 37  | SHIELD CAP                     |
| 11  | REACTOR                          | 38  | TEMPERATURE CONTROLLER         |
| 12  | FIXING BRACKET FOR CONTROL BOARD | 39  | CLAMPING PLATE FOR TRANSFORMER |
| 13  | CONTROL PCB                      | 40  | TRANSFORMER                    |
| 14  | FUSE                             | 41  | INSULATION PAPER               |
| 15  | BUZZ                             | 42  | DIODE                          |
| 16  | POWER SWITCH                     | 43  | RADIATOR                       |
| 17  | TURNING SWITCH                   | 44  | RECTIFIER                      |
| 18  | CONTROL PANEL                    | 45  | RECTIFIER PCB                  |
| 19  | CONNECTOR OF TORCH CORD          | 46  | CEMENT RESISTENCE              |
| 20  | PLUG                             | 47  | FIXING PLATE FOR RADIATOR      |
| 21  | TORCH CORD                       | 48  | ROUND CROSS BOLT               |
| 22  | WELDING TORCH                    | 49  | FLAT CROSS BOLT                |
| 23  | EARTH CLAMP                      | 50  | HEXAD BOLT                     |
| 24  | EARTH CORD                       | 51  | SPRING WASHER                  |
| 25  | QUICK CONNECTION                 | 52  | HEXAD CROSS BOLT               |
| 26  | QUICK SOCKET                     | 53  | FLAT WASHER                    |
| 27  | SOCKET                           |     |                                |

RUT032901