



## CS5016PS

NO.	DESCRIPTION	SPEC.	NO.	DESCRIPTION	SPEC.
1	Tapping screw	ST4.1x16-F	46	Ball bearing 6001-2RS	40x17x12
2	Tapping screw	ST4.1x32-F	47	Circlip for shaft 28	
3	Lock knob		48	Tapping screw	M5x12
4	Pab head screw	M5x45	49	Blade base	
5	small washer	Ø5	50	Saw blade	
6	Spring washer	Ø5	51	Flange	
7	Capacitor		52	Bolt	M8x20
8	Lock wheel		53	Blade guard cover	
9	Carbon brushes		54	Tapping screw	M4x12
10	Bush		55	Spindle lock button	
11	Brush holder		56	Spring	
12	Trigger		57	Bearing 6000 RS	8x22x7
13	Switch		58	Gear box	
14	Spring		59	Bush	
15	Push lever		60	Big gear	
16	Housing		61	Spindle	
17	Bush sleeve		62	Bevel indicator	
18	Bearing 607 RS	7x19x6	63	Bolt	M4x6
19	Rotor		64	Spring base	
20	Pan head tapping screw	ST4.1x65-F	65	Bolt	M6x22
21	Insulation plate of stator		66	Turn shaft	
22	Stator		67	Bolt	M6x12
23	Insulation end-plate		68	Washer	
24	Wind guard		69	Tapping screw	ST3.5x9-F
25	Fan		70	Bolt	M6x6
26	Tapping screw	ST2.9x10-F	71	bracket (front)	
27	Brush holder cap		72	Bolt	M6x20
28	Cord pressure plate		73	Washer	
29	Cord guard		74	Spring washer	
30	Depth lock pin		75	Bracket (rear)	
31	Torque spring		76	Washer	
32	Torque spring		77	Lock knob	
33	Bolt	M5x20	78	Bolt	M5x12
34	Fixed position plate		79	Washer	
35	Lock knob		80	Wave washer	
36	Indicator		81	Small washer	
37	Depth scaler		82	Adjustable knob	
38	Indicator base		83	Base plate	
39	Bolt	M6x33	84	Dust tube	
40	Bolt	M5x12	85	Rear cover	
41	Lock plate		86	Lift spring	
42	Spring of lock plate		87	Spindle lock sleeve	
43	Tapping screw	ST4.1x12-F	88	Dust tube adaptor	
44	Blade guard		89	Cable	
45	Gear box cover				