VER • GAS • HAND 54 POWER • GAS • HAND • TOOLS

GBE2400C

				R
	NO.	DESCRIPTION	NO.	DESCRIPTION
POWE	1	FEED HOPPER	35	CONNECTING LINE1
	2	SPLASH GUARD	36	CONNECTING LINE2
	3	PRESS BAR	37	MAGNETIC SWITCH
	4	SCREWAS • HAND	38	OVERCURRENT PROTECTOR
	5	KNOB	39	MOTOR CASING
	6	SPRING	40	MOTOR HOUSING COVER
	7	UP HOUSING	41	CAPACITOR
	8	LOCK RING	42	FAN
	9	SAFE PIN	43	BEARING 608Z
	10	SCREW	44	SCREW
	11	CLEAR MATERIAL ROD	45	MOTOR STENT (BACK)
	12	"H" TYPE SCREW	46	CARBON BRUSH
	13	INNER HEXAGON SCREW	48	STATOR
	14	FLAT GASKET	49	ROTOR
	15	SPRING WASHER 1	50	BEARING 6210Z
	16	FLANGE	51	SMALLBELT WHEEL
	17	SCREW	52	HEXNUT
	18	BLADE	53	WIND SHIELD
	19	CUTTER	54	GEARBOX COVER
	20	TRANSMISSION PIECE	55	BEARING 629Z
	21	AXIS GUIDE	56	ECCENTRIC WHEEL
	22	BLOCK BOARD	57	BIG BELT WHEEL
	23	SCREW	58	BELT
	24	DOWN HOUSING	59	GEARBOX COVER
	25	HOLD-DOWN NUT	60	BEARING 6003Z
	26	NUT FIXED BOARD	62	WHEEL COVER
	27	HEXNUT	64	SUPPORTING TUBE
	28	SWITCH	65	CONNECTING ROD
	29	SPRING WASHER 1	66	GASKET 2
	30	SWITCH FIXED BOARD	67	AXLE SETS
	31	SCREW	68	WHEEL
	32	CORD	69	RUBBISH BAG
	33	GUARD OV/FR • GA	888	MOTOR ASSEMBLY
	34	CABLE CLAMP		