



## MF5630C

NO.	DESCRIPTION	NO.	DESCRIPTION
1	Screw M8x12	25	Link Plate
2	Outside Flange	26	Plastic Housing
3	Spindle	27	Brush Holder
4	Rubber Casing	28	Carbon Brush
5	Circlip for Shaft 26	29	Lug
6	Spline Spring Washer	30	Switch
7	Bearing 6000	31	Cord Clip
8	Block of Toggler	32	Screw ST4.0x14
9	Bronze Bush	33	Spring
10	Screw ST4x27	34	Screw ST4.0x20
11	Reducer	35	Switch holder
12	Circlip for Shaft 5	36	adjustable-switch
13	Bearing 625	37	Back Housing
14	Sealing Washer	38	Screw ST4.0x10
15	Middle Cover	39	Screw ST4.0x16
16	Bearing 608	40	Rubber Sleeve
17	Block of Balance	41	Cord
18	Armature	42	Inductor
19	Bearing 607	501	HSS segment saw blade
20	Rubber Bush	502	Bi-metal E-CUT saw blade
21	Guide Wind Circle	503	Sanding pad
22	Screw ST4.0x50	504	Sanding paper
23	Stator	505	Inner hexagon spanner
24	Pull Brace		

ST20120301

Sturmi!  
POWER • GAS • HAND • TOOLS