



CD3112H.CD3114H.CD3118H

NO.	DESCRIPTION	NO.	DESCRIPTION
1	M SCREW /M5X22(L)	28	GEAR BOX COVER PLATE
2	CHUCK 3/8"-24UNF Ø0.8-Ø10	29	MOTOR PINION
3	CLUTCH CAP /PA66-GF30	30	M SCREW WITH WASHER /M3X6
4	SLEEVE	31	MOTOR MOUNTING
5	TORQUE CONTROL SPRING	32	MOTOR
6	TORQUE ADJUSTMENT WASHER/THK=1.5	33	INTERNAL WIRE
7	C-RING /Ø12	34	RING FOR MOTOR
8	FLAT WASHER	35	SPRING PLATE FOR TORQUE ADJUSTMENT
9	STEEL BALL /SØ3	36	SPEED CHANGE KNOB
10	BUSHING	37	SPRING PIN /Ø2.5X22
11	PIN /Ø5X5.5	38	HOUSING
12	STEEL BALL /SØ5	39	SWITCH
13	FRONT GEAR BOX HOUSING	40	ST SCREW
14	OUTPUT SHAFT	41	F-R LEVER
15	THE 3RD RING GEAR	42	ROPE FOR HUNG
16	THE 3RD PLANET GEAR	43	CONTACT PLATE ASS'Y
17	GEAR BOX PLATE	44	BATTERY PACK
18	GEAR BOX PLATE WITH GEAR	45	CLAMP FOR HUNG
19	REAR GEAR BOX HOUSING	46	SPRING FOR HUNG
20	SPEED CHANG LEVER	47	BOLT FOR HUNG
21	ST SCREW 2.8X14	48	SCREW
22	THE 3RD SUN GEAR	49	NUT
23	THE 2ND PLANET GEAR	50	SMALL BUSHING
24	THE 2ND RING GEAR	C	CHARGER
25	THE 2ND SUN GEAR	888	MOTOR ASSEMBLY
26	THE 1ST RING GEAR	999	GEAR BOX ASSEMBLY
27	THE 1ST PLANET GEAR		

ST20140707

Sturm!
POWER • GAS • HAND • TOOLS