



## CD3112H.CD3118H

NO.	DESCRIPTION	NO.	DESCRIPTION
1	M SCREW /M5X22(L)	27	THE 1ST PLANET GEAR
2	CHUCK 3/8"-24UNF Ø0.8-Ø10	28	GEAR BOX COVER PLATE
3	CLUTCH CAP /PA66-GF30	29	MOTOR PINION
4	SLEEVE	30	M SCREW WITH WASHER /M3X6
5	TORQUE CONTROL SPRING	31	MOTOR MOUNTING
6	TORQUE ADJUSTMENT WASHER/THK=1.5	32	MOTOR
7	C-RING /Ø12	33	INTERNAL WIRE
8	FLAT WASHER	34	RING FOR MOTOR
9	STEEL BALL /SØ3	35	SPRING PLATE FOR TORQUE ADJUSTMENT
10	BUSHING	36	SPEED CHANGE KNOB
11	PIN /Ø5X5.5	37	SPRING PIN /Ø2.5X22
12	STEEL BALL /SØ5	38	HOUSING
13	FRONT GEAR BOX HOUSING	39	SWITCH
14	OUTPUT SHAFT	40	ST SCREW
15	THE 3RD RING GEAR	41	F-R LEVER
16	THE 3RD PLANET GEAR	42	ROPE FOR HUNG
17	GEAR BOX PLATE	43	CONTACT PLATE ASS'Y
18	GEAR BOX PLATE WITH GEAR	44	BATTERY PACK
19	REAR GEAR BOX HOUSING	45	CLAMP FOR HUNG
20	SPEED CHANG LEVER	46	SPRING FOR HUNG
21	ST SCREW 2.8X14	47	BOLT FOR HUNG
22	THE 3RD SUN GEAR	48	SCREW
23	THE 2ND PLANET GEAR	49	NUT
24	THE 2ND RING GEAR	50	SMALL BUSHING
25	THE 2ND SUN GEAR	C	CHARGER
26	THE 1ST RING GEAR	999	GEAR BOX ASSEMBLY

ST20130916

POWER • GAS • HAND • TOOLS

Sturmi!  
POWER • GAS • HAND • TOOLS