



## GT-3510X

| NO. | DESCRIPTION     | NO. | DESCRIPTION         | NO. | DESCRIPTION                             |
|-----|-----------------|-----|---------------------|-----|---|
| 1   | SCREW           | 37  | TAPPING SCREW       | 74  | HEX BOLT                                |
| 2   | TUBE CONNECTOR  | 38  | LABEL               | 75  | PINION                                  |
| 3   | KNOB            | 39  | TAPPING SCREW       | 76  | INPUT SHAFT                             |
| 4   | RIVET           | 41  | SCREW               | 77  | BEARING 609(2 PCS)                      |
| 5   | CONNECTOR       | 42  | AUXILIARY HANDLE    | 78  | CIRCLIP FOR SHAFT                       |
| 6   | INSERT BUSH     | 43  | KNOB                | 79  | CIRCLIP FOR HOLE                        |
| 7   | SCREW           | 44  | HEX. BOLT           | 80  | SOFT SHAFT                              |
| 8   | SUPPORT         | 45  | SWITCH              | 81  | SOFT SHAFT SUPPORT                      |
| 9   | SOFT SHAFT      | 46  | SPRING              | 82  | SCREW                                   |
| 10  | ALU.TUBE        | 47  | BOUTTON             | 83  | PRESSURE BOARD                          |
| 11  | RUBBER LINER    | 48  | CAPACITOR           | 84  | ALU.TUBE                                |
| 12  | HOUSING         | 49  | TAPPING SCREW       | 85  | TAPPING SCREW                           |
| 13  | LABEL           | 50  | CORD ANCHORAGE      | 86  | INSERT TUBE                             |
| 14  | SCREW           | 51  | CORD GUARD          | 87  | ALU.TUBE CAP                            |
| 15  | BRACKET         | 52  | POWER CORD AND PLUG | 88  | LINE SPOOL GUARD                        |
| 16  | SCREW           | 53  | SCREW               | 89  | SMALL KNIFE                             |
| 17  | HOOK            | 54  | SPRING WASHER       | 90  | TAPPING SCREW                           |
| 18  | BELT            | 55  | FLAT WASHER         | 91  | KNIFE GUARD                             |
| 19  | SHAFT CONNECTOR | 56  | SPLINE BUSH         | 92  | LINE BOX                                |
| 20  | BRUSH HOLDER    | 57  | PRESSURE BOARD      | 93  | HOLE-PROTECTING COIN                    |
| 21  | FRONT COVER     | 58  | BLADE               | 94  | CONNECT BOLT                            |
| 22  | CARBON BRUSH    | 59  | PRESSURE BOARD      | 95  | SPRING                                  |
| 23  | BRUSH SUPPORT   | 60  | CIRCLIP FOR HOLE    | 96  | NYLON LINE                              |
| 24  | FLAT WASHER     | 61  | BEARING 6001        | 97  | BOBBIN                                  |
| 25  | SPRING WASHER   | 62  | WOODRUFF KEY        | 98  | SPOOL COVER                             |
| 26  | SCREW           | 63  | OUTPUT SHAFT        | 99  | SOCKET WRENCH                           |
| 27  | BEARING 608     | 64  | BIG GEAR            | 100 | BAR                                     |
| 28  | ROTOR           | 65  | BEARING 608         | 101 | MOTOR ASSEMBLY(21+27+28...+35)          |
| 29  | STATOR          | 66  | HEX. NUT            | 102 | LINE SPOOL ASSEMBLY(92+93...+98)        |
| 30  | SCREW           | 67  | BLADE GUARD         | 103 | GEAR BOX ASSEMBLY(60+61...+66+68...+79) |
| 31  | BEARING 608     | 68  | GEAR BOX            |     |   |
| 32  | FLAT WASHER     | 69  | FLAT WASHER         |     |   |
| 33  | SPRING WASHER   | 70  | SPRING WASHER       |     |   |
| 34  | REAR COVER      | 71  | HEX. BOLT           |     |   |
| 35  | FAN             | 72  | SCREW               |     |   |
| 36  | PCB             | 73  | SCREW               |     |   |