



## SCM2001CR

NO.	DESCRIPTION
1	housing
3	front cover
4	static blade
5	moving blade
6	nut M8
7	screw
8	wool ring
9	anti-loosen washer
10	screw M5X14
11	Hall PCB
12	screw M2.5X6
13	big gear
14	pin 5X9
15	magnet
16	gear box
17	gear ring
18	planet gear bracket
19	middle gear
20	planet gear
21	cone gear
22	circlip 20
23	bearing 699Z
24	motor gear
25	motor
26	spring
27	magnet
28	trigger
29	power button
30	PCB
31	connection board
32	tapping screw 3X20
33	tapping screw 3X10

ST-UK240130

Sturmaxo