



BC-1205X

| NO. | DESCRIPTION |
|-----|---------------------------------|
| 1 | MACHINE COVER |
| 2 | TAPPING SCREW |
| 3 | THERMAL CUT-OFF |
| 4 | TRANSFORMER |
| 5 | FIXING PLATE FOR TRANSFORMER |
| 6 | BOLT |
| 9 | NUT |
| 14 | RECTIFIER |
| 15 | ROUND SCREW |
| 16 | FLAT WASHER |
| 17 | SPRING WASHER |
| 18 | NUT |
| 19 | POWER CORD & PLUG |
| 20 | ANTI-PULL BLOCK |
| 21 | TAPPING SCREW |
| 22 | CHARGING CLAMP (RED) |
| 23 | CHARGING CABLE |
| 24 | CHARGING CLAMP(BLACK) |
| 25 | CHARGING CABLE |
| 26 | FUSE SET |
| 27 | FUSE PLATE |
| 28 | ON/OFF SWITCH |
| 29 | CURRENT METER |
| 30 | BASE PLATE |
| 101 | TRANSFORMER ASSEMBLY(3+4+5+6+9) |
| 102 | CHARGING CABLE & CLAMP (RED) |
| 103 | CHARGING CABLE & CLAMP (BLACK) |

BM20140718