



S1: Main switch;
 S2: Pressure switch;
 MS: Micro-switch
 M: Universal Motor;
 TP: Thermal protector;
 R: Rotor;
 L1: Winding;
 L2: Conductor(optional);
 C: Capacitor(optional);
 B: Bypass valve;
 P: Pressure;

绿田机械		材料	高压清洗机电气原理图(串激电机)
		重量	
设计	标准化	阶段标记	HPW electric diagram (universal motor)
审核	批准	页码	
会签	日期	比例	