



Sturm!

POWER • GAS • HAND • TOOLS

P1070

NO.	DESCRIPTION	NO.	DESCRIPTION
1	SCREW M4X16	32	COMPRESSION SPRING
2	CHIP COVER	33	RUBBER PACKING
3	NOB	34	FRONT BASE
4	SCALE PLATE	35	SCREW M5X18
6	HOUSING	36	BASE
8	NAME PLATE	37	RUBBER PIN 4
9	CORD GUARD	38	BEARING 608
10	CORD	39	DROM
11	STRAIN RELIEF	40	RUBBER PIN 4
12	SCREW M4X20	41	SCREW M4X55
13	CAPACITANCE	42	BRACKET
14	SWITCH	43	SCREW M4X20
15	HANDLE COVER	44	PULLEY 1
16	SCREW M4X25	45	BELT COVER
17	BEARING 6000	46	RUBBER PIN 4
20	ARMATURE	47	SCREW M4X25
22	BEARING 627	48	BELT
23	STATOR	49	PULLEY 2
24	SCREW M4X16	50	BEARING 6000
25	AUXILIARY BAFFLE PLATE	51	RUBBER PIN 4
26	SCREW M4X10	52	ADJUST PLATE
27	BEARING COVER	53	SCREW M4X5
28	CARBON BRUSH	54	DROM PLATE
29	BRUSH HOLDER CAP	55	BOLT M6X17
31	SCREW M5X10	56	INDUCTOR
32	COMPRESSION SPRING	57	BRUSH HOLDER

RU-ST20140905