



Sturmm![®]
POWER • GAS • HAND • TOOLS

WP9751A

NO.	DESCRIPTION	NO.	DESCRIPTION
1	SCREW	16	INSULATOR PAPER
2	SCREW	17	MOTOR BODY
3	CORD SLEEVE	18	ROTOR
4	CABLE & PLUG	19	SHAFT KEY
5	COVER	20	BALL BEARING 6202
6	SCREW	21	BOLT
7	WASHER	22	SEAL
8	CAPACITOR PRESSER	23	FRONT COVER
9	CAPACITOR	24	"O"RING
10	END COVER	25	MECHANICAL SEAL
11	SPRING WASHER	26	IMPELLER
12	BALL BEARING 6202	27	LOCKING NUT
13	HEAT PROTECTOR	28	PUMP BODY
14	STATOR	29	SCREW
15	WIRE	101	STATOR ASSEMBLY(13+14+15+16+17)

ST20110425

Sturmm![®]
POWER • GAS • HAND • TOOLS

Sturmm![®]
POWER • GAS • HAND • TOOLS