



WP9770S

NO.	DESCRIPTION	NO.	DESCRIPTION
1	CABLE AND PLUG	290	MOTOR FRONT COVER
2	FLOATING SWITCH	30	SKELETON SEALING RING
3	SCREW	32	FRONT ADJUSTMENT SHIM
4	HANDLE	33	IMPELLER
5	NUT	34	NUT
6	SCREW	35	O SEALING RING
7	MAIN PUMP HOUSING	36	PRESSURE RING
8	O SEALING RING	37	SCREW
9	BEHIND COVER	38	EARTHING SHIM
10	CABLE SLEEVE	39	SEAL
11	CABLE CLAMP	40	RUBER SEAL
12	CAPACITOR	41	BASE
13	CABLE CLAMP BLOCK	42	FUNDUS
14	SCREW	43	SCREW
15	MOTOR COVER	44	SYPHON
16	WAVEFORM SHIM	45	O SEALING RING
18	BEARING 6201Z	46	OUTPUT TIE-IN
19	ROTOR	50	CAPACITOR COVER
20	BEARING 6201Z	51	MECHANICAL SEALING LATEX
21	NUT	310	MOTOR BUSH
22	STEEL BALL	350	STRAIGHT CONNECTOR
23	O SEALING RING	550	METAL WASHER
24	AIR OUTER	52	WIRE SLEEVE
25	STATOR	53	CIRCLIP
26	SKELETON SEALING RING	101	STATOR ASSEMBLY(25+26+28+290 +30+270A+310+550)
270A	MOTOR FRONT SLEEVE		
28	O SEALING RING		

ST20121123-02

POWER • GAS • HAND • TOOLS

Sturm!
POWER • GAS • HAND • TOOLS